

Editors Note: The following story describes a rotating equipment, compressor, failure. It shows, that even for fixed equipment, the dynamics (typically more than just one) leading to failure often, usually involve, and are heavily dependent upon operating practices, as well as design, fabrication, materials, etc. The true causes are often not evident or can be mis-diagnosed if we don't understand the impact operations' practices, and other factors, contribute. A good and timely example is the multi-faceted deterioration mechanism of high temperature hydrogen attack, where operating practices can have a large impact on the progression of damage, leading to failure. We hope you find valuable lessons in the following account as readers continue to develop healthy, questioning minds that seek to understand the "whole picture" in our pursuit of excellence.

FRACTURE ANALYSIS

**Cliff Knight, PE, President and Chief Engineer
KnightHawk Engineering, Inc.**

E-mail questions or comments to inquiries@inspectioneering.com



Cliff Knight

The morning meeting at the plant was a tough one for you. As an area engineer you are not satisfied with the information you are receiving from your team's investigation into a major compressor wreck that has happened once again. The conclusion from the team has always been corrosion fatigue, and suggestions have been made to change the material to a more exotic type. The cost of the impeller would be more than five times the original equipment manufacturer (OEM), and have a long delivery time. One of the aspects of the work conducted by all the "high powered" experts that really bugs you is that all the sister plants around the world with the same process have the same impeller material, and yet do not experience these failures. Also the plant has a long history of running in this service with this material in other pumps and compressors. So in your mind "things just don't add up". The words "corrosion fatigue" resonate in your mind. Also, there is no doubt in your mind that the team is one of the best in the business.

Any area engineer should take a broad base look at the facts and ask questions. Questions were asked about this not happening with other pieces of equipment in sister plant using the same materials. In fact, the team was correct with their conclusions. The cause of the problem was corrosion fatigue. However, the key term here is fatigue. Fatigue translates to the fact that in the impeller reverse loading occurs, which means in practical terms that a dynamic stress was present. The fact that the impeller failed suggests the endurance limit was exceeded. After putting all the facts together it's time to "dig deeper" to see what is really going on. For the impeller to have failed, the endurance limit must have been exceeded. You ask the team to show you the Goodman Diagram so you can see the interaction of the steady state and dynamic stresses. The team does not produce a diagram, because none was ever developed. The reason is the team focused on "corrosion" as being the major player in this "corrosion fatigue" problem.

A typical allowable dynamic stress in an impeller on the Goodman diagram is $\frac{1}{4}$ of the tensile stress of the material. This assumes the material is good, and meets the ASTM

standard for the material. However, corrosion can cause pitting, and reduce the endurance limit by another factor of two to five. Does this mean we have found the root cause of the failure? The answer is a flat "No!" No Goodman, Campbell, or interference diagram was developed.

The next step is to look at the process, and determine the exact details of what may be different. There must be some reason for the change. To do this requires evaluating the transient and steady state operation of the compressor. This might require additional instrumentation be incorporated into the process to better capture the process transient events.

In this particular problem, the molecular weight of the process changed during a transient period of operation when the plant was running at a higher capacity. This caused an excitation of the cavity acoustics, which ultimately led to the excitation of the impeller blades. A forcing function was present that matched a natural frequency of the impeller. Higher level analysis determined the impeller would have failed anyway, even without "derated" endurance conditions present. In other words, the dynamic stresses were so high that they would exceed the endurance limit of the metal with no corrosion.

A recommended approach to this problem is as follows:

1. Put together a team consisting of Process, Controls, Mechanical, and Metallurgical experts. The Area engineer should facilitate the team or even an "outsider" who is independent. In that case, the Area engineer should be involved with the team as team member.
2. Perform a Metallurgical analysis of the fracture surface to characterize the type of fracture.
3. Perform a process analysis looking at both the steady state and transient operations. Evaluate any changes that have occurred such as a slight increase in speed of the compressor for example.
4. Field services should be performed to capture the

dynamic pressures and vibrations. This information would be useful to determine if any active cavity acoustics are present or secondary wake disturbances.


5. A complete mechanical review should be conducted, and detailed finite element models should be made of the impeller. Interference diagrams should be created and evaluated. Be aware that some diagrams do not consider cavity acoustics, and secondary wake disturbances at the tip of the impeller. In this case finite element acoustic models should be developed of the cavity and computational fluid dynamics models should be conducted of the flow path.

6. A root cause failure analysis should be conducted based on all the information collected.
7. Design changes can be made to fix the problem.

Often the fixes can be easily made. In the example discussed above a lower rpm during the process transient where the plant was running at a lower molecular weight fixed the problem.


As discussed earlier CFD modeling of the Impeller can look at local disturbances that can act as a forcing function that may be the source of the problem.

Figure 1 : CFD Modeling of Impeller




The Goodman Diagram below indicates points of crack initiation.

Figure 2: Goodman Diagram



As indicated in Figure 3 are typical interference diagrams. As discussed earlier, these do not consider cavity acoustics or secondary wake disturbances.

Many of these failures are complex and detailed in nature, and all work conducted should be reviewed and approved by a professional engineer competent in machinery failure analysis.



Clifton (Cliff) Troy Knight, P.E.
President and Chief Engineer
Knighthawk Engineering, Inc.

Cliff is President and co-founder of KnightHawk Engineering, Incorporated since 1991. He is a Professional Engineer with 31 years of experience. Besides his corporate responsibilities as President of KnightHawk, Cliff is also Chief Engineer and Supervising Professional for the Engineering Consulting Group. As Chief Engineer, Cliff serves as the lead technical professional for major multidiscipline investigations into industrial static and rotating equipment failures. Cliff holds five US Patents and is a registered Professional Engineer. Cliff has a BSME from Louisiana State University 1980.